


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-058	Smoke	9/8/2008	ADS/TM	S13EE1016MH	Dry	Yes	1,545.58



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-058	Smoke	9/8/2008	ADS/TM	S13EE1016MH	Dry	Yes	1,545.58

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13EE1016G1	S13EE1016MH	S13EE1015MH	214.2067	8
S13EE1027G1	S13EE1027MH	S13EE1016MH	42.01518	8
S13EE1013G1	S13EE1013MH	S13EE1008MH	163.9737	8
S13EE1010G1	S13EE1010MH	S13EE1001MH	164.2626	8
S13EE1008G1	S13EE1008MH	S13EE1016MH	45.28586	8
S13EE1032G1	S13EE1032DE	S13EE1015MH	270.2708	8
S13EE1015G1	S13EE1015MH	S13EE1001MH	65.49269	8
S13EE1001G1	S13EE1001MH	S13EE1014MH	229.7611	8
S13GG1001G1	S13GG1001MH	S13EE1016MH	145.8131	8
S15EE1015G1	S15EE1015MH	S13EE1027MH	204.494	8

Observations & Photos

Obs_ID S1028-058-OB01

Address 2663 Oswego Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13EE1027MH

Comments Smoke from cleanout in front yard. 2663 Oswego Ave



Picture \S1028-058-OB01-P01.jpg

Comments Front of house, 2663 Oswego Ave

Obs_ID S1028-058-OB02

Address 2657 Oswego Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13EE1027MH

Comments Smoke from cleanout in front yard. 2657 Oswego Ave



Picture \S1028-058-OB02-P01.jpg

Comments Front of house, 2657 Oswego Ave

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-058	Smoke	9/8/2008	ADS/TM	S13EE1016MH	Dry	Yes	1,545.58

Obs_ID S1028-058-OB03

Address 2653 Oswego Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S15EE1015MH

Comments Smoke from cleanout in front yard. 2653 Oswego Ave



Picture \S1028-058-OB03-P01.jpg

Comments Front of house, 2653 Oswego Ave

Obs_ID S1028-058-OB04

Address Oswego Ave & Pimlico Rd

Status Public

Source Catch Basin

Location Curb

Nearest MH S13EE1016MH

Comments Smoke from catch basin along curb at SE corner of Oswego Ave & Pimlico Rd



Picture \S1028-058-OB04-P01.jpg

Comments Oswego Ave & Pimlico Rd looking north

Obs_ID S1028-058-OB05

Address 4007 Pimlico Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13EE1013MH

Comments Smoke from cleanout in front yard. 4007 Pimlico Rd



Picture \S1028-058-OB05-P01.jpg

Comments Front of house, 4007 Pimlico Rd

Obs_ID S1028-058-OB06

Address 4033 Park Heights Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13EE1015MH

Comments Smoke from cleanout in front yard. 4033 Park Heights Ave



Picture \S1028-058-OB06-P01.jpg

Comments Front of house, 4033 Park Heights Ave

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-058	Smoke	9/8/2008	ADS/TM	S13EE1016MH	Dry	Yes	1,545.58

Obs_ID S1028-058-OB07

Address Oswego Ave & Pimlico Rd

Status Public

Source Catch Basin

Location Curb

Nearest MH S13EE1016MH

Comments Smoke from catch basin along curb at SW corner of Oswego Ave & Pimlico Rd



Picture \S1028-058-OB07-P01.jpg

Comments Oswego Ave & Pimlico Rd looking west

Obs_ID S1028-058-OB08

Address 2658 Oswego Ave

Status Public

Source Catch Basin

Location Curb

Nearest MH S13EE1016MH

Comments Smoke from catch basin along curb at NW corner of Oswego Ave & Pimlico Rd



Picture \S1028-058-OB08-P01.jpg

Comments Side of house, 2658 Oswego Ave